Appendix C: Asbestos register (example)

BUILDING/WORKPLACE ADDRESS:

NAME OF COMPETENT PERSON:

Date identified	Location	Product type	Description	Friable or non-friable	Condition	Amount	Accessibility	Tested	Test result	Action taken
15 June 2022	*Ground floor changing cubicle*	*Vinyl flooring*	*Square tile with black adhesive*	*Non-friable*	*Excellent*	*2600mm x 2000mm*	*Accessible – used every day*	*Yes – 30 June 2022*	*Positive*	*Labelled, avoid disturbance*
15 June 2022	*Service access EH-3*	*Pipework*	*Gaskets*	*Non-friable*	*Good*	*Small amount between pipes*	*Accessed by maintenance staff only*	*No*	*Assume positive*	*Labelled*

Date identified	Location	Product type	Description	Friable or non-friable	Condition	Amount	Accessibility	Tested	Test result	Action taken